

A. EQUIPMENT TO BE SUPPLIED BY THE ADMINISTRATION


QUANTITY	ITEM DESCRIPTION
90 SF	SHEET ALUMINUM SIGN (WATCH FOR EMERGENCY VEHICLES WHEN FLASHING) WITH MAST ARM MOUNTING HARDWARE
1 EA 2 EA	TYPE "G" SIGNAL CABINET-POLE MOUNTED PUSHBUTTON

B. EQUIPMENT TO BE SUPPLIED AND/OR INSTALLED BY THE CONTRACTOR

ITEM NO QUANT	ITY ITEM DESCRIPTION			
1001 1 EA	MAINTENANCE OF TRAFFIC			
2001 1 CY	TEST PIT EXCAVATION			
8001 5 CY	F&I CONCRETE FOR SIGNAL FOUNDATION			
8006 1 EA	CUT, CLEAN GALVANIZE AND CAP SIGNAL STRUCTURE			
8018 2 EA	INSTALL PUSHBUTTON			
8019 1 EA	INSTALL CABINET AND CONTROLLER-POLE MOUNT			
8024 100 LF	F&I 2" SCH 80 RIGID PVC ELECTRICAL CONDUIT-TRENCHED			
8027 12 LF	F&I 3" SCH 80 RIGID PVC ELECTRICAL CONDUIT-TRENCHED			
8033 2 EA	F&I ELECTRICAL HANDHOLE			
8043 240 LF	F&I 3-CONDUCTOR NO 14AWG ELECTRICAL CABLE			
8044 85 LF	Total O Consider the Time Electrical Consideration			
8066 1 EA	TOTAL STATE			
	(120/240 V, 1 PHASE 3 WIRE SYSTEM)			
8077 1 EA				
8084 4 EA				
NEG 1 LS	7 57777 7778 778 778 778 778 778 778 778			
	NECCESARY HARDWARE TO MOUNT TO BLOCK WALL			
GENERAL NOTES				
· —	**************************************			

1. UTILITIES SHOWN ARE SCHEMATIC ONLY AND SHOULD NOT BE CONSIDERED COMPLETE.
THE CONTRACTOR SHALL CONTACT MISS UTILITY PRIOR TO BEGINNING ANY WORK TO
VERIFY EXACT LOCATIONS OF UTILITIES. IF THE CONTRACTOR PERCEIVES THAT A CONFLICT
MAY EXIST, THEY SHALL CONTACT THE PROJECT ENGINEER IMMEDIATLEY TO RESOLVE
THE CONFLICT.

WIRING DIAGRAM



REVISIONS	APPROVALS	MARYLAND DOT - STATE HIGHWAY ADMINISTRATION
	INAM 8-14-00 TEAM LEADER, TRAFFIC ENGINEERING DESIGN DIVISION	Office of Traffic & Safety TRAFFIC ENGINEERING DESIGN DIVISION
	ASST. CHIEF TRAFFIC ENGINEERING DESIGN DIVISION	MD 346 (OCEAN CITY RD) @ PARSONSBURG VFD GENERAL INFORMATION SHEET FIREHOUSE HIB
	CHIEF, TRAFFIC ENGINEERING DESIGN DIVISION	DRAWN BY: C. STRAIN F.A.P. NO. TS NO.
		CHECKED BY: M. RUCKER S.H.A. NO. WTS7A571857 4047 SHEET NO. SCALE: NO SCALE COUNTY: WICOMICO T.I.M.S. NO.
	DIRECTOR, TRAFFIC & SAFETY	DATE: 7/31/00 LOG MILE: E 048 2 OF 2